

Model Name: RJ-4030

Network Port	Power consumption		Default Timer Values	
	Networked Standby mode	Off mode	To Networked Standby mode	To Off mode
USB Port1	1.2W	0.4W	0min	10min
Bluetooth	1.4W	0.4W	0min	10min
RS-232C	1.3W	0.4W	0min	10min
All network ports activated and connected	1.5W	0.4W	0min	10min

How to enable/disable Bluetooth

To activate the Bluetooth function:

Press and hold the ⏻ (Power) button to turn the printer on and then press and hold the Bluetooth button.

To deactivate the Bluetooth function:

Turn off the printer.